

Health Check Report



Report generated on 1/01/2019 0:00:01 AM

Your equipment

Equipment-ID	12345678
Description	LIFT 1 - PASSENGER LIFT
Address	36-38 Lord Street Botany 2019

Summary


Equipment Status Ok	Action info No action required
-------------------------------	--



Statistics

Total number of trips	81,071	Trips in this month	5,083
Total distance	1,443.06 km		

Trips in this month



Summary

<ul style="list-style-type: none"> Special operation mode <ul style="list-style-type: none"> Emergency power operation mode Fire service mode Overload mode Reservation mode Out of service mode Overtemperature Cabin light <ul style="list-style-type: none"> Car light working Light curtain of door <ul style="list-style-type: none"> Light curtain working Buttons & indicators inside cabin <ul style="list-style-type: none"> Car operating panels, buttons, indicators Buttons & indicators outside cabin <ul style="list-style-type: none"> Landing operating panels, buttons, indicators Traffic management system Cabin levelling accuracy <ul style="list-style-type: none"> Car landing position at door level Relevelling check Final limit switches (upper and bottom limits) 	<ul style="list-style-type: none"> Cabin movement & speed <ul style="list-style-type: none"> Car movement interruptions Car position in the shaft Uncontrolled movements Brake contact operation Motor speed Car speed at floor level Main contactors operation Motor electrical resistance Frequency convertor connection Door opening & closing <ul style="list-style-type: none"> Door opening/closing operations Car door drive and contacts Car door force limiter Car and landing door safety chain Door preopening at zone level Overload measurement <ul style="list-style-type: none"> Load measuring device communication Load measuring device calibration 	<ul style="list-style-type: none"> Tele-Monitoring Evacuation system, battery Internal Systems <ul style="list-style-type: none"> Car roof safety device Car control unit communication Safety chain interruptions Unexpected restarts Car travel time to destination floor Traction media lifetime Miscellaneous
Environmental conditions <ul style="list-style-type: none"> Main power outages 0 power outages detected Overtemperature 0 days where limits were exceeded 		

Monitoring of the equipment is done via our remote monitoring system, receiving technical information and detecting abnormal behavior. The scope of the remote inspection consists of

- Normal operation
- ▲ Anomaly identified
- Unit stopped
- Currently no data

